

DRILLING LOG		DIVISION Southwestern		INSTALLATION Galv Dist, Eng Div		SHEET OF SHEETS	
1. PROJECT GIWW Colorado River, Matagorda Bay				10. SIZE AND TYPE OF BIT			
2. LOCATION (Coordinates or Station)				11. DATUM FOR ELEVATION SHOWN (TBM or MSL) Sta. 504+000 North Bank, 15.0 Offset North			
3. DRILLING AGENCY Dept of the Army, GD, Corps of Engineers				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number)		3ST-21		13. TOTAL NO. OF OVERBURDEN SAMPLES TAKEN		DISTURBED 2 Jars	
5. NAME OF DRILLER Black				14. TOTAL NUMBER CORE BOXES		UNDISTURBED 2 Cont	
6. DIRECTION OF HOLE <input type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED _____ DEG. FROM VERT.				15. ELEVATION GROUND WATER		16. DATE HOLE STARTED 2 Dec COMPLETED 2 Dec 1966	
7. THICKNESS OF OVERBURDEN				17. ELEVATION TOP OF HOLE		18. TOTAL CORE RECOVERY FOR BORING %	
8. DEPTH DRILLED INTO ROCK				19. SIGNATURE OF INSPECTOR			
9. TOTAL DEPTH OF HOLE 22.0							
ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOV- ERY e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g	
0.0	11.0		Water				
11.0	14.0		Gray clay, kelly and 2 rods v/soft			Jar 1	0.0
14.0	18.5		Gray clay, no resistance v/soft, kelly and 2 rods			Jar 2	0.0
18.5	20.0		Brown silty clay, hard			Cont. 1	4.50
20.0	22.0		Brown silty clay, v/stiff			Cont. 2	3.00
			BOTTOMED				
			Tide 1.6 at 11:30 AM				