

DRILLING LOG		DIVISION Southwestern		INSTALLATION Galv Dist, Eng Div		SHEET OF SHEETS	
1. PROJECT GIWW - Colorado River to Matagorda Bay				10. SIZE AND TYPE OF BIT			
2. LOCATION (Coordinates or Station)				11. DATUM FOR ELEVATION SHOWN (TBM or MSL) Sta. 458+000 North Side Channel			
3. DRILLING AGENCY Dept of the Army, GD, Corps of Engineers				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number)		3ST-1		13. TOTAL NO. OF OVERBURDEN SAMPLES TAKEN		DISTURBED 3 Jars	
5. NAME OF DRILLER Black				14. TOTAL NUMBER CORE BOXES			
6. DIRECTION OF HOLE ☐ VERTICAL ☐ INCLINED _____ DEG. FROM VERT.				15. ELEVATION GROUND WATER			
7. THICKNESS OF OVERBURDEN				16. DATE HOLE		STARTED 29 Nov	
8. DEPTH DRILLED INTO ROCK				17. ELEVATION TOP OF HOLE		COMPLETED 29 Nov 66	
9. TOTAL DEPTH OF HOLE 22.5				18. TOTAL CORE RECOVERY FOR BORING %			
				19. SIGNATURE OF INSPECTOR			
ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOV- ERY e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g	
0.0	11.5		Water				
11.5	15.0		Black muck			Jar 1	
15.0	21.0		Black mucky clay			Jar 2	
21.0	22.5		Black mucky clay to brown sand, changed at 22.0			Jar 3	
22.5			BOTTOMED				
			Note - Unable to recover in 2.5 runs Kelly and 2 drill rods penetrated to 22.5 w/no resistance				
			Tide +1.0 at 12:45				