

DRILLING LOG		DIVISION Southwestern		INSTALLATION Galv Dist, Eng Div		SHEET OF SHEETS	
1. PROJECT GIWW Colorado River - Matagorda Bay				10. SIZE AND TYPE OF BIT			
2. LOCATION (Coordinates or Station)				11. DATUM FOR ELEVATION SHOWN (TBM or MSL) Sta. 508+039 North Bank, Offset 25.0' North			
3. DRILLING AGENCY Dept of the Army, GD, Corps of Engineers				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number)		3ST-23		13. TOTAL NO. OF OVERBURDEN SAMPLES TAKEN		DISTURBED 2 Jars	
5. NAME OF DRILLER Black				14. TOTAL NUMBER CORE BOXES		UNDISTURBED 3 Cont	
6. DIRECTION OF HOLE ☐ VERTICAL ☐ INCLINED _____ DEG. FROM VERT.				15. ELEVATION GROUND WATER			
7. THICKNESS OF OVERBURDEN				16. DATE HOLE		STARTED 6 Dec	
8. DEPTH DRILLED INTO ROCK				17. ELEVATION TOP OF HOLE		COMPLETED 6 Dec 1966	
9. TOTAL DEPTH OF HOLE		22.0		18. TOTAL CORE RECOVERY FOR BORING		%	
19. SIGNATURE OF INSPECTOR							
ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOVERY e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g	
0.0	10.5		Water				
10.5	13.0		Gray sandy clay, soft			Jar 1	0.25
13.0	16.0		Gray sandy clay, soft			Jar 2	0.25
16.0	18.0		Brown clay w/sand layers w/cal nods, small, stiff			Cont. 1	1.50
18.0	20.0		Brown clay w/sand layers w/cal nods, w/siltstone hard			Cont. 2	4.00
20.0	22.0		Brown silt w/clay seams v/stiff			Cont. 3	2.75
			BOTTOMED				
			Tide +1.7 at 10:00 AM				