

DRILLING LOG		DIVISION Southwestern		INSTALLATION Galv Dist, Eng Div		SHEET OF SHEETS	
1. PROJECT GIWW Colorado River - Matagorda Bay				10. SIZE AND TYPE OF BIT			
2. LOCATION (Coordinates or Station)				11. DATUM FOR ELEVATION SHOWN (TBM or MSL) Sta. 466+000			
3. DRILLING AGENCY Black				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number)				13. TOTAL NO. OF OVERBURDEN SAMPLES TAKEN		DISTURBED 2 Cont	UNDISTURBED 2 Jars
5. NAME OF DRILLER Black				14. TOTAL NUMBER CORE BOXES			
6. DIRECTION OF HOLE ☐ VERTICAL ☐ INCLINED _____ DEG. FROM VERT.				15. ELEVATION GROUND WATER		16. DATE HOLE STARTED 29 Nov COMPLETED 29 Nov 66	
7. THICKNESS OF OVERBURDEN				17. ELEVATION TOP OF HOLE			
8. DEPTH DRILLED INTO ROCK				18. TOTAL CORE RECOVERY FOR BORING %			
9. TOTAL DEPTH OF HOLE 22.0				19. SIGNATURE OF INSPECTOR			
ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOVERY e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g	
0.0	7.0		Water				
7.0	9.5		Brown silty clay, soft			Cont. 1	0.25
9.5	12.0		Brown silty clay, med			Cont. 2	0.50
12.0	17.0		Red silty clay			Jar 1	
17.0	22.0		Red silty clay			Jar 2	
			BOTTOMED				
			Tide .7 at 3:30 PM				