

DRILLING LOG		DIVISION Southwestern	INSTALLATION Galv Dist, Eng Div	SHEET OF SHEETS
1. PROJECT GIWW Colorado River - Matagorda Bay		10. SIZE AND TYPE OF BIT		
2. LOCATION (Coordinates or Station)		11. DATUM FOR ELEVATION SHOWN (TBM or MSL) Sta. 490+000 South Bank Channel		
3. DRILLING AGENCY Dept of the Army, GD, Corps of Engineers		12. MANUFACTURER'S DESIGNATION OF DRILL		
4. HOLE NO. (As shown on drawing title and file number) 3ST-14		13. TOTAL NO. OF OVERBURDEN SAMPLES TAKEN	DISTURBED 2 Jars	UNDISTURBED 1 Cont
5. NAME OF DRILLER Black		14. TOTAL NUMBER CORE BOXES		
6. DIRECTION OF HOLE <input type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED _____ DEG. FROM VERT.		15. ELEVATION GROUND WATER		
7. THICKNESS OF OVERBURDEN		16. DATE HOLE	STARTED 1 Dec	COMPLETED 1 Dec 66
8. DEPTH DRILLED INTO ROCK		17. ELEVATION TOP OF HOLE		
9. TOTAL DEPTH OF HOLE 22.0		18. TOTAL CORE RECOVERY FOR BORING %		
		19. SIGNATURE OF INSPECTOR		

ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOVERY e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g
0.0	13.2		Water			
13.2	18.0		Gray mucky clay, v/soft No resistance			Jar 1
18.0	20.0		Brown clayey sand			Cont. 1
20.0	22.0		Brown silty sand			Jar 2
			BOTTOMED			
			Tide 1.0 at 3:45 PM			