

DRILLING LOG		DIVISION Southwestern	INSTALLATION Galv Dist, Eng Div	SHEET OF SHEETS
1. PROJECT GIWW Colorado River to Matagorda Bay		10. SIZE AND TYPE OF BIT		
2. LOCATION (Coordinates or Station)		11. DATUM FOR ELEVATION SHOWN (TBM or MSL) Sta. 464+00 South Side Channel		
3. DRILLING AGENCY Dept of the Army, GD, Corps of Engineers		12. MANUFACTURER'S DESIGNATION OF DRILL		
4. HOLE NO. (As shown on drawing title and file number) 3ST-4		13. TOTAL NO. OF OVERBURDEN SAMPLES TAKEN	DISTURBED 2 Jars	UNDISTURBED 1 Cont
5. NAME OF DRILLER Black		14. TOTAL NUMBER CORE BOXES		
6. DIRECTION OF HOLE <input type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED _____ DEG. FROM VERT.		15. ELEVATION GROUND WATER		
7. THICKNESS OF OVERBURDEN		16. DATE HOLE	STARTED 29 Nov	COMPLETED 29 Nov 66
8. DEPTH DRILLED INTO ROCK		17. ELEVATION TOP OF HOLE		
9. TOTAL DEPTH OF HOLE 22.0		18. TOTAL CORE RECOVERY FOR BORING %		
		19. SIGNATURE OF INSPECTOR		

ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOVERY e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g
0.0	12.8		Water			
12.8	18.0		Gray mucky clay, tr sand v/soft, unable to recover w/2.5 runs, penetrated material w/weight of kelly and 2 drill rods			Jar 1
18.0	20.0		Gray clay, tr sand, v/soft			Cont. 1 0.0
20.0	22.0		Gray fine loose sand			Jar 2
			BOTTOMED			
			Tide .7 at 3:00 PM			