

DRILLING LOG		DIVISION Southwestern		INSTALLATION Galv Dist, Eng Div		SHEET OF SHEETS	
1. PROJECT GIWW Colorado River - Matagorda Bay				10. SIZE AND TYPE OF BIT			
2. LOCATION (Coordinates or Station)				11. DATUM FOR ELEVATION SHOWN (TBM or MSL) Sta. 486+000 South Side Channel			
3. DRILLING AGENCY Dept of the Army, GD, Corps of Engineers				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number)		3ST-12		13. TOTAL NO. OF OVERBURDEN SAMPLES TAKEN		DISTURBED 2 Jars	
5. NAME OF DRILLER Black				UNDISTURBED 2 Cont			
6. DIRECTION OF HOLE <input type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED _____ DEG. FROM VERT.				14. TOTAL NUMBER CORE BOXES			
7. THICKNESS OF OVERBURDEN				15. ELEVATION GROUND WATER			
8. DEPTH DRILLED INTO ROCK				16. DATE HOLE		STARTED 1 Dec	
9. TOTAL DEPTH OF HOLE 22.0				COMPLETED 1 Dec 1966		17. ELEVATION TOP OF HOLE	
18. TOTAL CORE RECOVERY FOR BORING				19. SIGNATURE OF INSPECTOR			
ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOVERY e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g	
0.0	12.0		Water				
12.0	18.0		Gray mucky clay, v/soft No resistance weight of Kelly and 2 drill rods			Jar 1	
18.0	20.0		Brown clay, hard			Cont. 1 4.00	
20.0	21.0		Same as above, v/stiff			Cont. 2 3.00	
21.0	22.0		Brown silty sand, dense			Jar 2	
			BOTTOMED				
			Tide 1.7 at 8:30 AM				