


Hole No. 3ST-12							
DRILLING LOG		DIVISION Southwestern		INSTALLATION Galveston Dist. Eng Div		SHEET OF SHEETS	
1. PROJECT Port Aransas-Corpus Christi Waterway				10. SIZE AND TYPE OF BIT			
2. LOCATION (Coordinates or Station)				11. DATUM FOR ELEVATION SHOWN (TBM or MSL)			
3. DRILLING AGENCY U. S. Army Corps of Engineers				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number)		3ST-12		13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED 3 Jars	
5. NAME OF DRILLER Eck				14. TOTAL NUMBER CORE BOXES		UNDISTURBED 2 Cont	
6. DIRECTION OF HOLE ☐ VERTICAL ☐ INCLINED _____ DEG. FROM VERT.				15. ELEVATION GROUND WATER			
7. THICKNESS OF OVERBURDEN				16. DATE HOLE		STARTED 29 Apr	
8. DEPTH DRILLED INTO ROCK				17. ELEVATION TOP OF HOLE		COMPLETED 29 Apr 1964	
9. TOTAL DEPTH OF HOLE 52.0				18. TOTAL CORE RECOVERY FOR BORING %			
				19. SIGNATURE OF INSPECTOR			
ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOV- ERY e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g	
0.0	40.0		Water				
40.0	41.0		Dark gray silty, redeposited material			No sample	
41.0	42.0		Dark tan clay w/gray silt and shell			Jar 1	
42.0	44.0		Light gray sand, loose			Cont. 1 .05	
44.0	45.5		Light gray v/fine sand 44.0-44.5 No blows 44.5-45.0 8 blows 45.0-45.5 10 blows			Jar 2	
45.5	48.0		Washed, same as above			No sample	
48.0	50.0		Light gray fine sand w/small amount of clay, soft			Cont. 2 0.25	
50.0	52.0		Light gray sand w/cemented sandstone @ bottom Bottomed Tide +2.0 @ 1:00 PM			Jar 3	

LOG OF BORING NO. 35T-12
Tide + 2.0 @ 1:00 pm

LOCATION:



DEPTH TO WATER
IN BORING.

DATE _____