

Hole No. 3ST-29						
DRILLING LOG						
DIVISION Sout. stern						
INSTALLATION Galv Dist, E. Div						
SHEET OF SHEETS						
1. PROJECT Port Aransas-Corpus Christi Waterway						
10. SIZE AND TYPE OF BIT						
2. LOCATION (Coordinates or Station)						
11. DATUM FOR ELEVATION SHOWN (TBM or MSL) Tide +2.3 @ 3:00 PM						
3. DRILLING AGENCY U. S. Army Corps of Engineers						
12. MANUFACTURER'S DESIGNATION OF DRILL						
4. HOLE NO. (As shown on drawing title and file number) 3ST-29						
13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN 2 Jars						
UNDISTURBED 3 Cont						
5. NAME OF DRILLER Eck						
14. TOTAL NUMBER CORE BOXES						
15. ELEVATION GROUND WATER						
6. DIRECTION OF HOLE						
16. DATE HOLE STARTED 4 May COMPLETED 4 May 1964						
7. THICKNESS OF OVERBURDEN						
17. ELEVATION TOP OF HOLE						
8. DEPTH DRILLED INTO ROCK						
18. TOTAL CORE RECOVERY FOR BORING %						
9. TOTAL DEPTH OF HOLE 52.0						
19. SIGNATURE OF INSPECTOR						
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOVERY	BOX OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant)
a	b	c	d	e	f	g
0.0	38.0		Water			
38.0	40.0		No recovery, same as above			No sample
40.0	42.0		Black oily clay, v/soft wet			Jar 1
42.0	44.0		Light tan clay w/cal nod v/stiff			Cont. 1 2.5
44.0	46.0		Light tan clay w/traces of silt on bottom, medium			Cont. 2 0.50
46.0	48.0		Same as below, sand			No sample
48.0	49.0		Coarse gray sand w/clay particles			
			48.0-48.5 No count			
			48.5-49.0 24 blows			
			49.0-49.5 16 blows			Jar 2
49.5	50.0		Washed, same as above			
50.0	52.0		Light gray clay w/sand layers hard			Cont. 3 4.50
			Bottomed			

54

LOCATION:

DATE _____