Hole No. 78-13C

DRILLING LOG	DIVISION South Western	INSTALLATION Galveston D.V.	SHEET 1 OF 1 SHEETS

1. PROJECT GIWW Aransas Pass - Tributary Channel	10. SIZE AND TYPE OF BIT
2. LOCATION (Coordinates or Station) Sta. 212+50 140' rt ℄	11. DATUM FOR ELEVATION SHOWN (TBM or MSL)
3. DRILLING AGENCY USCEC	12. MANUFACTURER'S DESIGNATION OF DRILL Failing 1500
4. HOLE NO. (As shown on drawing title and file number) 78-13C	13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN: DISTURBED 1; UNDISTURBED 3
5. NAME OF DRILLER Burt Black	14. TOTAL NUMBER CORE BOXES
6. DIRECTION OF HOLE ☑ VERTICAL ☐ INCLINED ____ DEG. FROM VERT.	15. ELEVATION GROUND WATER
7. THICKNESS OF ~~OVERBURDEN~~ WATER DEPTH 4.5 @ 2:00	16. DATE HOLE: STARTED 2 June '78; COMPLETED 2 June '78
8. DEPTH DRILLED INTO ROCK	17. ELEVATION TOP OF HOLE
9. TOTAL DEPTH OF HOLE	18. TOTAL CORE RECOVERY FOR BORING %
	19. SIGNATURE OF INSPECTOR A. B. Price

ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOVERY e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g
			0.0' to 4.5': water		4.5	
	5		4.5' to 11.0' Dark gray silty clay, massive, very soft. Common to abundant shells.		1C 1.3' 2.00 9.0	Drilling: 4.5' to 22.5' 3 inch shelby tube,
	10				10.0'	washed down to 10.0'
			11.0' to 11.5' Dark gray silty clay very abundant shells grades downward to gradational contact.		2C 1.3'	
			11.5' to 19.0' Gray silty sand. Loose, massive. Fine grained. Sand spherical, well rounded, quartose.		12.5	
	15				15.0'	washed down to 15.0'
					3J 17.0'	
	20		19.0' to 22.5' Light green, massive, fine grained loose sand. Sand spherical, well rounded, quartose.		20.0' 4C 2.00	Washed down to 20.0'
			TD 22.5'.		22.5'	

ENG FORM 1836 MAR 71 PREVIOUS EDITIONS ARE OBSOLETE. PROJECT HOLE NO.

(TRANSLUCENT)