


DRILLING LOG		DIVISION Southwestern		INSTALLATION Galv Dist, Eng Div		SHEET OF SHEETS	
1. PROJECT Port Aransas-Corpus Christi WW				10. SIZE AND TYPE OF BIT			
2. LOCATION (Coordinates or Station)				11. DATUM FOR ELEVATION SHOWN (TBM or MSL) Tide #2 @ 2:00 PM			
3. DRILLING AGENCY U. S. Army Corps of Engineers				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number)		3ST-6		13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED UNDISTURBED 5 Cont	
5. NAME OF DRILLER Eck				14. TOTAL NUMBER CORE BOXES			
6. DIRECTION OF HOLE ☐ VERTICAL ☐ INCLINED _____ DEG. FROM VERT.				15. ELEVATION GROUND WATER			
7. THICKNESS OF OVERBURDEN				16. DATE HOLE		STARTED 28 Apr COMPLETED 28 Apr 1964	
8. DEPTH DRILLED INTO ROCK				17. ELEVATION TOP OF HOLE			
9. TOTAL DEPTH OF HOLE 52.0				18. TOTAL CORE RECOVERY FOR BORING %			
				19. SIGNATURE OF INSPECTOR			
ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOV- ERY e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g	
0.0	41.0		Water				
41.0	42.0		Drk gray redeposited silt			No sample	
42.0	44.0		Drk gray silt streaked on top w/tan clay v/stiff			Cont. 1 3.0	
44.0	46.0		Tan silty clay, v/stiff			Cont. 2 3.75	
46.0	48.0		Tan clay w/traces of silt v/stiff			Cont. 3 2.75	
48.0	50.0		Light tan clay, v/stiff			Cont. 4 3.75	
50.0	52.0		Light tan clay, v/stiff			Cont. 5 3.0	
			Bottomed				

Port Aransas
Corpus Christi
Waterway

LOG OF BORING NO. 35T-6 (31)
Tide +2 @ 2:00 PM

TYPE: 3" Shelby Tube

LOCATION:



COMPLETION DEPTH 52.0'
DATE 28 April '64

DEPTH TO WATER
IN BORING

DATE