

DRILLING LOG		DIVISION Southwestern		INSTALLATION Galv Dist, Eng Div		SHEET OF SHEETS	
1. PROJECT Small Boat Harbor				10. SIZE AND TYPE OF BIT			
2. LOCATION (Coordinates or Station) Port Isabel, Texas				11. DATUM FOR ELEVATION SHOWN (TBM or MSL) Tide -1.1 @ 9:30 AM Tide -0.5 @ 12:30 PM			
3. DRILLING AGENCY U. S. Army Corps of Engineers				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number) 4A-10				13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED 1 Jar	
5. NAME OF DRILLER Watts				14. TOTAL NUMBER CORE BOXES			
6. DIRECTION OF HOLE ☐ VERTICAL ☐ INCLINED _____ DEG. FROM VERT.				15. ELEVATION GROUND WATER		16. DATE HOLE 28 Jan	
7. THICKNESS OF OVERBURDEN				17. ELEVATION TOP OF HOLE		COMPLETED 28 Jan 1964	
8. DEPTH DRILLED INTO ROCK				18. TOTAL CORE RECOVERY FOR BORING		%	
9. TOTAL DEPTH OF HOLE 11.0				19. SIGNATURE OF INSPECTOR			
ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOV- ERY e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g	
0.0	3.5		Water				
3.5	11.0		Dark to light gray clayey muck, v/soft w/org. mat.			Jar 1	
			Bottomed				

SMALL BOAT HARBOR
PORT ISABEL

LOG OF BORING NO. 4A-10
Tide -1.1 @ 9:30 AM
-0.5 @ 12:30 PM

TYPE: 4" Auger

LOCATION:

DEPTH - FT.	SYMBOL	SAMPLES	DESCRIPTION OF MATERIAL	BLOWS PER FT.	UNIT DRY WT. LBS / CU FT	POCKET PENETROMETER TONS / SQ. FT.			ELEVATION - FT.		
						PLASTIC LIMIT	WATER CONTENT, %	LIQUID LIMIT			
SURF EL.						0.5	1.0	1.5	2.0	2.5	3.0
						10	20	30	40	50	60
			Water 0.0-3.3								
5	C		Dark Gray clayey muck								
10	L		LS-190 0-2-98								
15											
20											
25											
30											
35											
40											
45											
50											

COMPLETION DEPTH 11.0'
DATE 28 JAN '69

DEPTH TO WATER
IN BORING

DATE