Probing Logs

Project:	**BUG Bay Bottom Survey**	**Driller:**	Continental Dredging
		Engineer:	Clay Bryant
Location:	**Galveston Bay**		
		Vessel:	M. V. Captain Dale
		Pump:	5HP 3" Honda

Date:	May 21, 1992				
Hole Number:	I-16	**Easting:**	3310084	**Northing:**	629972
Time:	10:53	**Station:**		**Range:**	
Sounding Depth:	12 feet	**Bottom of Probe:**	37	**Penetration:**	25

Bottom Character : Soft Mud

17 - 17 : soft mud

17 - 19 : shell layer

19 - 37 : soft mud, sticky

Character of Finish : soft **Tide:**

Date:	May 21, 1992				
Hole Number:	J-16	**Easting:**	3314986	**Northing:**	629821
Time:	11:20	**Station:**		**Range:**	
Sounding Depth:	11 feet	**Bottom of Probe:**	38	**Penetration:**	27

Bottom Character : Soft Mud

11 - 13 : soft mud

13 - 18 : medium shell

18 - 38 : soft mud with shell fragments

Character of Finish : soft **Tide:**