Probing Logs

Project:	**BUG Bay Bottom Survey**	**Driller:**	Continental Dredging
		Engineer:	Clay Bryant
Location:	**Galveston Bay**		
		Vessel:	M. V. Captain Dale
		Pump:	5HP 3" Honda

Date:	**May 28, 1992**				
Hole Number:	**H-14**	**Easting:**	3304695	**Northing:**	639701
Time:	10:14	**Station:**		**Range:**	
Sounding Depth:	12 feet	**Bottom of Probe:**	38	**Penetration:**	26

Bottom Character : Soft

12 - 17 : soft mud

17 - 19 : shell layer

19 - 36 : soft mud, shell layer at 36 feet

36 - 38 : soft mud

Character of Finish : soft **Tide:**

Date:	**May 21, 1992**				
Hole Number:	**H-15**	**Easting:**	3305135	**Northing:**	634619
Time:	9:55	**Station:**		**Range:**	
Sounding Depth:	11 feet	**Bottom of Probe:**	30	**Penetration:**	19

Bottom Character : Soft Mud

11 - 20 : soft mud

20 - 30 : dense shell

Character of Finish : dense shell, semi-refusal **Tide:**