

DRILLING LOG		DIVISION Southwestern	INSTALLATION Galv Dist, Eng Div		SHEET OF SHEETS	
1. PROJECT Sabine Neches Spoil Disposal Area			10. SIZE AND TYPE OF BIT			
2. LOCATION (Coordinates or Station)			11. DATUM FOR ELEVATION SHOWN (TBM or MSL)			
3. DRILLING AGENCY U. S. Army Corps of Engineers			12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number) 3ST-20			13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED UNDISTURBED 8 Cont	
5. NAME OF DRILLER Caraway			14. TOTAL NUMBER CORE BOXES			
6. DIRECTION OF HOLE ☐ VERTICAL ☐ INCLINED _____ DEG. FROM VERT.			15. ELEVATION GROUND WATER			
7. THICKNESS OF OVERBURDEN			16. DATE HOLE		STARTED 14 Apr COMPLETED 14 Apr 1964	
8. DEPTH DRILLED INTO ROCK			17. ELEVATION TOP OF HOLE			
9. TOTAL DEPTH OF HOLE 16.0			18. TOTAL CORE RECOVERY FOR BORING %			
			19. SIGNATURE OF INSPECTOR			

ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOV- ERY e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g
0.0	2.0		Light gray tan sandy clay stiff			Cont. 1 1.25
2.0	4.0		Light gray tan sandy clay stiff			Cont. 2 1.50
4.0	6.0		Light tan sandy clay, stiff			Cont. 3 1.25
6.0	8.0		Gray sandy clay, soft			Cont. 4 0.25
8.0	10.0		Light tan sandy clay, v/stiff			Cont. 5 2.25
10.0	12.0		Gray clay w/small amount of sand and shell, med			Cont. 6 0.50
12.0	14.0		Dark gray clay, soft			Cont. 7 0.25
14.0	16.0		Light tan gray clay, stiff			Cont. 8 1.25
			Bottomed Water 5.0			