

U.S. ARMY CORPS OF ENGINEERS

DEPTH, FEET		SAMPLE NO.	SAMPLE NO.	PEN./TORVANE	SPT.-BLOW COUNT	BORING NO. <u>92-175</u> DATE: BEGIN <u>7-31-92</u> PAGE <u>111</u> JOB NO. <u>146548</u> COMPLETE <u>7-31-92</u> Thin Walled Tube PROJECT <u>DISPOSAL AREA #5</u> ☒ 3" ☐ 6" LOCATION <u>BROWNSVILLE SHIP CHANNEL</u> ELEVATION OF HOLE <u>PERMANENTLY OPEN CHANNEL</u> MANUFACTURER'S DESIGNATION OF DRILL RIG <u>C-1000 Marsh Buggy</u> GROUNDWATER: DEPTH <u>2.00</u> ft., ELEV <u> </u> ft., at end of Drilling WEATHER <u>PARTLY CLOUDY & WINDY</u> DRILLER <u>SCOTT</u> LOGGER <u>JOHN</u>				
		COLOR	MATERIAL TYPE	CONSISTENCY	SECONDARY CONSTITUENTS	STRUCTURAL FEATURES AND COMMENTS				
0										
1	1.5	BROWN	CLAY	STIFF						
2	2.0	"	"	VERY STIFF						
3	0.75	"	"	MEDIUM STIFF			GRAY 4'-6'			
4	0.5	BROWN	CLAY	MEDIUM STIFF	SILTY		6'-10'			
5	1.0	"	"	STIFF	"		-w/SILT LAYER BELOW 8 FT			
10										
15										
20										
25										
30										
35										

SUMMARY OF LABORATORY TEST RESULTS

[illegible]

Geotest Engineering, Inc.