

LOG OF BORING

PROJECT: White Point Island Restoration Nueces Bay - Corpus Christi, Texas										PROJECT NO. 1600-0159 BORING NO. B-14 DATE 9/20/2000 ELEV. NA			
CLIENT: Shiner Moseley & Associates, Inc. Corpus Christi, Texas													
SHEET 1 of 1													
FIELD DATA				LABORATORY DATA							DRILLING METHOD (S) :		
SOIL SYMBOL	DEPTH (FT)	SAMPLES	N: BLOWS/FT P: TONS/SQ FT T: TON/SQ FT PERCENT RECOVERY/ ROCK QUALITY DESIGNATION	ATTERBERG LIMITS (%)			MOISTURE CONTENT	DRY DENSITY POUNDS/CU.FT	SHEAR STRENGTH (KIPS/SQ FT)	FAILURE STRAIN (%)	CONFINING PRESSURE (POUNDS/SQ IN)	MINUS NO. 200 SIEVE (%)	
				LIQUID LIMIT	PLASTIC LIMIT	PLASTICITY INDEX							
													LL
GROUNDWATER INFORMATION: Depth of water from surface to mudline at time of drilling was 3.8 ft.													
DESCRIPTION OF STRATUM													
5		X	N=WH	49	51	18	33						Clay, very soft, dark gray, with trace shell fragments and sand pockets. (CH)
		X	N=WH	59									
		X	N=WH	40									
		X	N=WH	46									
		X	N=WH	47									
10													TOTAL DEPTH = 10 FT (Below Mudline)
15													
20													
N - STANDARD PENETROMETER TEST RESISTANCE P - POCKET PENETROMETER RESISTANCE T - POCKET TORVANE SHEAR STRENGTH										REMARKS: PLATE 15			