

LOG OF BORING

PROJECT: White Point Island Restoration
Nueces Bay - Corpus Christi, Texas

CLIENT: Shiner Moseley & Associates, Inc.
Corpus Christi, Texas

PROJECT NO.	1600-0159
BORING NO.	B-1
DATE	9/19/2000
ELEV.	NA

SHEET 1 of 1

FIELD DATA		LABORATORY DATA										DRILLING METHOD (S) :
SOIL SYMBOL	DEPTH (FT)	SAMPLES N: BLOWS/FT P: TONS/SQ.FT T: TON/SQ.FT PERCENT RECOVERY/ ROCK QUALITY DESIGNATION	MOISTURE CONTENT	ATTERBERG LIMITS (%)			DRY DENSITY POUNDS/CU.FT	SHEAR STRENGTH (KIPS/SQ.FT)	FAILURE STRAIN (%)	CONFINING PRESSURE (POUNDS/SQ.IN)	MINUS NO. 200 SIEVE (%)	Wet Rotary
				LIQUID LIMIT	PLASTIC LIMIT	PLASTICITY INDEX						
				LL	PL	PI						
												GROUNDWATER INFORMATION: Depth of water from surface to mudline at time of drilling was 2.7 ft.
												DESCRIPTION OF STRATUM
		N=WH										Shell fragments, with sand and trace clay, gray, very loose.
		N=WH										
	5	N=4										-loose, below 4.5'.
		N=3									5	
	10	N=WH										No sample recovery, 8.5' to 10'.
												TOTAL DEPTH = 10 FT (Below Mudline)
	15											
	20											
N - STANDARD PENETROMETER TEST RESISTANCE P - POCKET PENETROMETER RESISTANCE T - POCKET TORVANE SHEAR STRENGTH												REMARKS: PLATE 2