

LOG OF BORING

PROJECT: White Point Island Restoration
Nueces Bay - Corpus Christi, Texas

CLIENT: Shiner Moseley & Associates, Inc.
Corpus Christi, Texas

PROJECT NO. 1600-0159

BORING NO. B-3

DATE 9/20/2000

ELEV.	NA
-------	----

SHEET 1 of 1

FIELD DATA				LABORATORY DATA								DRILLING METHOD (S) :		
SOIL SYMBOL	DEPTH (FT)	SAMPLES	N: BLOWS/FT P: TONS/SQ FT T: TON/SQ FT PERCENT RECOVERY/ ROCK QUALITY DESIGNATION	MOISTURE CONTENT	ATTEBERG LIMITS (%)			DRY DENSITY POUNDS/CU.FT	SHEAR STRENGTH (KIPS/SQ.FT)	FAILURE STRAIN (%)	CONFINING PRESSURE (POUNDS/SQ IN)	MINUS NO. 200 SIEVE (%)	GROUNDWATER INFORMATION:	
					LIQUID LIMIT	PLASTIC LIMIT	PLASTICITY INDEX						Depth of water from surface to mudline was not measured at this location.	
					LL	PL	PI						DESCRIPTION OF STRATUM	
			T=.04	58	67	23	44						Clay, very soft, gray, some trace shell fragments and sand pockets. (CH)	
			T=.05	58										
	5		*	84								76		
			*	68										
	10												No sample recovery, 8' to 10'.	
													TOTAL DEPTH = 10 FT (Below Mudline)	
													*Sample disturbed.	
	15													
	20													
N - STANDARD PENETROMETER TEST RESISTANCE P - POCKET PENETROMETER RESISTANCE T - POCKET TORVANE SHEAR STRENGTH													REMARKS: PLATE 4	