

LOG OF BORING

PROJECT: White Point Island Restoration
Nueces Bay - Corpus Christi, Texas

CLIENT: Shiner Moseley & Associates, Inc.
Corpus Christi, Texas

PROJECT NO. 1600-0159

BORING NO. B-7

DATE 9/20/2000

ELEV. NA

SHEET 1 of 1

FIELD DATA				LABORATORY DATA								DRILLING METHOD (S) :	
SOIL SYMBOL	DEPTH (FT)	SAMPLES	N: BLOWS/FT P: TONS/SQ FT T: TON/SQ FT PERCENT RECOVERY/ ROCK QUALITY DESIGNATION	MOISTURE CONTENT	ATTEBERG LIMITS (%)			DRY DENSITY POUNDS/CU.FT	SHEAR STRENGTH (KIPS/SQ FT)	FAILURE STRAIN (%)	CONFINING PRESSURE (POUNDS/SQ IN)	MINUS NO. 200 SIEVE (%)	Wet Rotary
					LIQUID LIMIT	PLASTIC LIMIT	PLASTICITY INDEX						
					LL	PL	PI						
GROUNDWATER INFORMATION:													
Depth of water from surface to mudline at time of drilling was 3.4 ft.													
DESCRIPTION OF STRATUM													
	0	T=.02	138									Clay, very soft, dark gray, with shell fragments. (CH)	
													No sample recovery, 2' to 4'.
	5	T=.01	96										-with trace shell fragments, below 4'. -with sand pocket, below 4.5'.
		T=.04	82	73	23	50							
		T=.02	117										
10	TOTAL DEPTH = 10 FT (Below Mudline)												
	15												
	20												
N - STANDARD PENETROMETER TEST RESISTANCE P - POCKET PENETROMETER RESISTANCE T - POCKET TORVANE SHEAR STRENGTH													REMARKS: PLATE 8