

LOG OF BORING

PROJECT: White Point Island Restoration
Nueces Bay - Corpus Christi, Texas

CLIENT: Shiner Moseley & Associates, Inc.
Corpus Christi, Texas

PROJECT NO.	1600-0159
BORING NO.	B-9
DATE	9/20/2000
ELEV.	NA

SHEET 1 of 1

FIELD DATA				LABORATORY DATA								DRILLING METHOD (S) :		
SOIL SYMBOL	DEPTH (FT)	SAMPLES	N: BLOWS/FT P: TON/SQ FT T: TON/SQ FT PERCENT RECOVERY/ ROCK QUALITY DESIGNATION	MOISTURE CONTENT	ATTERBERG LIMITS (%)			DRY DENSITY POUNDS/CU.FT	SHEAR STRENGTH (KIPS/SQ FT)	FAILURE STRAIN (%)	CONFINING PRESSURE (POUNDS/SQ IN)	MINUS NO. 200 SIEVE (%)	GROUNDWATER INFORMATION:	
					LL	PL	PI						Depth of water from surface to mudline at time of drilling was 2.3 ft.	
													DESCRIPTION OF STRATUM	
			*	116									Clay, dark gray. (CH)	
			T=.04	126	107	36	71							
	5		T=.03	118										
			T=.01	94									-with shell fragments, below 6'.	
				99								15	Shell fragments, with sand and some clay, gray.	
	10												TOTAL DEPTH = 10 FT (Below Mudline)	
													*Sample disturbed.	
	15													
	20													
N - STANDARD PENETROMETER TEST RESISTANCE P - POCKET PENETROMETER RESISTANCE T - POCKET TORVANE SHEAR STRENGTH													REMARKS: PLATE 10	
													FLUORO-COUNTING - Gulf Coast Testing	