

July 8, 2003

Attn.: Mr. Gerald Hauske, P.E.

RETL Job No.: C0300572

BOLIVAR PENNINSULA CAPLEN/GILCREST BEACH NOURISHMENT

GLO LEPRRA Project No. 1087

Galveston County, Texas

Grab Samples (% Passing)						
SIEVE SIZE	GS-1	GS-2	GS-3	GS-4	GS-5	GS-6
#10	100	100	100	99	100	99
#20	100	100	100	97	97	97
#40	100	100	100	95	94	95
#60	99	99	100	92	90	90
#70	94	95	98	85	85	83
#100	47	46	62	42	59	51
#140	8	7	10	7	12	10
#200	3	2	2	2	2	2

The laboratory-testing program was conducted in general accordance with applicable ASTM Specifications. The results of these tests are to be found on the accompanying Boring Logs and Grain Size Distribution Curves provided as attachments.

If significant changes are made in the character or location of the proposed project, a consultation should be arranged to review any changes with respect to the prevailing soil conditions. At that time, it may be necessary to perform additional field operations in order to provide supplementary information.


Often, because of design and construction details that occur on a project, questions arise concerning soil conditions, and RETL would be pleased to continue it's role as the Geotechnical Engineer during project implementation.

If you have any questions or comments, please contact us at (361) 883-4555.

Sincerely,



Mark C. Rock, P.E.
Vice President of Operations



Attachments

Boring Location Plan
Boring Logs
Grain Size Distribution Curves