

October 16, 2006
Attn.: Mr. Josh Carter
RETL Job No.: G106505

PROPOSED SAN LUIS PASS PROJECT PHASE 2
West Galveston Bay
Freeport, Texas

	BORING D01			BORING D02			
SIEVE SIZE	1-2.5'	6'-7.5'	18.5'-20'	3.5'-5'	8.5'-10'	13.5'-15'	23.5'-25'
#10	95	99	100	100	100	99	100
#20	91	97	100	100	100	99	100
#40	87	96	100	100	100	99	99
#60	84	95	100	99	100	98	99
#70	82	93	100	98	100	97	96
#80	77	90	99	95	98	94	90
#100	50	60	81	68	61	56	60
#120	26	30	32	34	24	24	28
#140	14	19	18	17	12	12	14
#200	5.7	9.0	5.7	4.2	3.2	2.2	2.8
#230	5.0	7.8	5.0	3.6	2.8	1.8	2.5
Color	2.5Y 5/2	2.5Y 4/1	2.5Y 4/1	2.5Y 5/2	2.5Y 3/1	2.5Y 5/2	2.5Y 5/2
Description	Gray Brown	Dk. Gray	Dk. Gray	Gray Brown	Vry. Dk. Gray	Gray Brown	Gray Brown

Closing

Pursuant to instructions, no further laboratory testing or engineering analyses have been performed. If you have any questions or comments, please contact us at (361) 883-4555.

Sincerely,



Christopher A. Rock, P.E.
Branch Manager

Attachments: Boring Location Plan
Boring Logs C01 through C13 & D01 and D02
Grain Size Analysis
Key to Soil Classifications


SHEET 1 of 1



CLIENT:	Coast and Harbor Engineering, Inc.
PROJECT:	Proposed San Luis Pass Project Phase 2
LOCATION:	W. Galveston Bay; Freeport, Texas
NUMBER:	G106505

DATE(S) DRILLED: 9/21/06 - 9/21/06

FIELD DATA					LABORATORY DATA					DRILLING METHOD(S):			
SOIL SYMBOL	DEPTH (FT)	SAMPLE NUMBER	SAMPLES	N: BLOWS/FT P: TONS/SQ.FT T: TONS/SQ.FT PERCENT RECOVERY/ ROCK QUALITY DESIGNATION	MOISTURE CONTENT (%)	ATTEBERG LIMITS			DRY DENSITY POUNDS/CU.FT	COMPRESSIVE STRENGTH (TONS/SQ.FT)	MINUS NO. 200 SIEVE (%)	Disturbed Samples	
						LIQUID LIMIT	PLASTIC LIMIT	PLASTICITY INDEX				GROUNDWATER INFORMATION:	
						LL	PL	PI				Groundwater encountered at 1' during drilling. Dry and caved at 1' upon completion of drilling operation.	
												SURFACE ELEVATION: N/A	
												DESCRIPTION OF STRATUM	
		SS S-1	X	N = 17							6	<u>POORLY GRADED SAND</u> , 2.5Y 5/2 gray brown, medium.	
	5	SS S-2	X	N = 20								Same as above, 2.5Y 5/2 gray brown.	
		SS S-3	X	N = 6							9	Same as above, 2.5Y 4/1 dark gray, loose.	
	10	SS S-4	X	N = 3								<u>POORLY GRADED SAND</u> , 2.5Y 3/1 very dark gray, very loose.	
		SS S-5	X	N = 9								Same as above, 2.5Y 3/2 very dark gray brown, loose.	
	15	SS S-6	X	N = 19								Same as above, 2.5Y 3/1 very dark gray, medium.	
		SS S-7	X	N = 12							6	<u>POORLY GRADED SAND</u> , 2.5 4/1 dark gray, medium.	
	20												
		SS S-8	X	N = 5								Same as above, 2.5 4/1 dark gray, loose.	
	25											Boring terminated at a depth of 25' below the ground surface.	
N - STANDARD PENETRATION TEST RESISTANCE P - POCKET PENETROMETER RESISTANCE T - POCKET TORVANE SHEAR STRENGTH												REMARKS: Soil Sampling performed by Envirocore, Inc, a drilling subcontractor to RETL, at N29.0799 deg W95.1265 deg.	



COBBLES	GRAVEL		SAND			SILT OR CLAY
	coarse	fine	coarse	medium	fine	

Specimen Identification		Classification				LL	PL	PI	Cc	Cu
●	D01	1.0							1.15	1.79
Specimen Identification		D100	D60	D30	D10	%Gravel	%Sand	%Silt	%Clay	
●	D01	1.0	2	0.16	0.129	0.09	0.0	89.3	5.7	




Rock Engineering & Testing Laboratory
4910 Neptune Street
Corpus Christi, TX 78405
Telephone: 361-883-4555
Fax: 361-883-4711

GRAIN SIZE DISTRIBUTION

Project: Proposed San Luis Pass Project Phase 2

Location: W. Galveston Bay, Freeport, Texas

Number: G106505



COBBLES	GRAVEL		SAND			SILT OR CLAY
	coarse	fine	coarse	medium	fine	

Specimen Identification	Classification	LL	PL	PI	Cc	Cu
● D01 6.0					1.34	1.93

Specimen Identification	D100	D60	D30	D10	%Gravel	%Sand	%Silt	%Clay
● D01 6.0	2	0.15	0.125	0.078	0.0	90.0	9.0	

GRAIN SIZE DISTRIBUTION

Project: Proposed San Luis Pass Project Phase 2
 Location: W. Galveston Bay; Freeport, Texas
 Number: G106505



Rock Engineering & Testing Laboratory
 4910 Neptune Street
 Corpus Christi, TX 78405
 Telephone: 361-883-4555
 Fax: 361-883-4711

