

DEPARTMENT OF THE ARMY DIVISION <u>Southwestern</u> INSTALLATION <u>Galv Dist, Eng Div</u>			1. PROJECT Port Aransas-Corpus Christi WW		SHEET <u> </u> OF <u> </u>	
DRILLING LOG			2. LOCATION (Coordinates or Station) Corpus Christi Bay			
4. HOLE NO. (As shown on drawing title and file No.) 3ST-13			3. DRILLING AGENCY U. S. Army Corps of Engineers			
6. DIRECTION OF HOLE ☐ VERTICAL ☐ INCLINED DEGREES WITH VERTICAL			7. THICKNESS OF OVERBURDEN		8. DEPTH DRILLED INTO ROCK	
10. SIZE AND TYPE OF BIT Shelby Tube - 3"			11. DATUM FOR ELEVATION SHOWN (TBM or MSL)		9. TOTAL DEPTH OF HOLE 52.0	
13. TOTAL NO. OF OVERBURDEN SAMPLES TAKEN DISTURBED 4 Jars UNDISTURBED 7 Cont			14. TOTAL NO. CORE BOXES		15. ELEV. GROUND WATER	
17. ELEV. TOP OF HOLE			18. TOTAL CORE RECOVERY FOR BORING (%)		16. DATE HOLE STARTED 26 Apr COMPLETED 26 Apr 1963	
19. SIGNATURE OF INSPECTOR						
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOVERY	BOX OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant)
0.0	25.0		Water			
25.0	27.5		Gray sticky clay, v/soft			Cont. 1
27.5	30.0		Gray sticky clay, v/soft			Cont. 2
30.0	32.5		Gray sticky clay, v/soft			Cont. 3
32.5	35.0		Gray sticky clay, v/soft			Cont. 4
35.0	37.5		Gray sticky clay, v/soft			Cont. 5
37.5	40.0		Gray sticky clay, v/soft			Cont. 6
40.0	42.0		Gray sticky clay to gray sticky clay w/shell, v/soft changed @ 42.2			Cont. 7
42.0	42.5		Gray sticky clay w/shell			
42.5	45.0		Gray sticky clay w/shell v/soft			Jar 1
45.0	47.5		Gray sticky clay w/shell v/soft			Jar 2
47.5	50.0		Gray sticky clay w/shell v/soft			Jar 3
50.0	52.0		Gray sticky clay w/shell v/soft			Jar 4
			Bottomed in above Tide +1.9 @ 8:00 Wind 15-20 MPH			

Tide +1.9 @ 8:00

LOCATION: Corpus Christi Bay

SWN 266(C)
22 AUG 62