

BORING LOG FIELD DATA											
Project <u>HARBOR ISLAND, PORT ARANSAS, TEXAS</u>						Location <u>2,532, 409'; 754,672</u>			Date <u>4 JUNE 1974</u>		
Drill Rig <u>FAILING 1500</u>						Inspector <u>LANGFORD</u>			Operator <u>YOUNGER</u>		
Levee District <u>GALVESTON</u>						Job No. _____			Surface elev _____		
									Boring No. <u>74-138</u>		
SAMPLE NUMBER	DATE TAKEN <u>1974</u>	STRATUM		DRIVE		SAMPLE		TYPE OF SAMPLER	CONTAINER	POCKET PENETROMETER VALUE	CLASSIFICATION AND REMARKS
		FROM	TO	FROM	TO	FROM	TO				
	<u>4 JUNE</u>	<u>0.0</u>	<u>30.0</u>								<u>WATER DEPTH 1230 HOURS</u>
<u>1</u>				<u>0.0</u>	<u>3.0</u>	<u>0.2</u>	<u>0.8</u>	<u>BOSTERBERG</u>	<u>JAR</u>	<u>0.0</u>	<u>GRAY SILTY, SANDY CLAY VERY SOFT.</u>
<u>1</u>						<u>0.8</u>	<u>1.9</u>		<u>TUBE</u>		<u>VANE SHEAR 0.03 (15)</u>
<u>1</u>						<u>1.9</u>	<u>3.0</u>		<u>TUBE</u>		
				<u>3.0</u>	<u>5.0</u>						<u>WASHED</u>
<u>2</u>				<u>5.0</u>	<u>8.0</u>	<u>6.7</u>	<u>7.2</u>		<u>JAR</u>	<u>0.0</u>	<u>VANE SHEAR 0.03 (15)</u>
<u>2</u>						<u>7.2</u>	<u>8.0</u>		<u>TUBE</u>		
				<u>8.0</u>	<u>10.0</u>						<u>WASHED</u>
<u>3</u>				<u>10.0</u>	<u>13.0</u>	<u>10.1</u>	<u>10.8</u>		<u>JAR</u>	<u>0.0</u>	<u>VANE SHEAR 0.08 (40)</u>
<u>3</u>						<u>10.8</u>	<u>11.9</u>		<u>TUBE</u>		<u>WITH SAND LAYERS.</u>
<u>3</u>						<u>11.9</u>	<u>13.0</u>		<u>TUBE</u>		
				<u>13.0</u>	<u>17.0</u>						<u>WASHED</u>
<u>4</u>		<u>20.0</u>	<u>17.0</u>	<u>20.0</u>	<u>17.5</u>	<u>18.0</u>			<u>JAR</u>	<u>0.25</u>	<u>SOFT. VANE SHEAR 0.10 (50)</u>
<u>4</u>					<u>18.0</u>	<u>19.0</u>			<u>TUBE</u>		
<u>4</u>					<u>19.0</u>	<u>20.0</u>			<u>TUBE</u>		
											<u>TOTAL DEPTH 20.0' (110.0')</u>

Date_____ Classified by_____

[illegible]

