

DRILLING LOG		DIVISION <i>Southwest</i>		INSTALLATION <i>Galv. Dist</i>		Hole No. <i>78-131</i>	
						SHEET <i>1</i> OF 3 SHEETS	
1. PROJECT <i>Passive Area on Houston Ship Channel, Tex.</i>				10. SIZE AND TYPE OF BIT			
2. LOCATION (Coordinates or Station) <i>34-51+000</i>				11. DATUM FOR ELEVATION SHOWN (TBM or MSL)			
3. DRILLING AGENCY <i>U.S. CRC</i>				12. MANUFACTURER'S DESIGNATION OF DRILL <i>Palmer 1500</i>			
4. HOLE NO. (As shown on drawing title and file number) <i>78-131</i>				13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED <i>4-Jug</i> UNDISTURBED <i>12-Gr</i>	
5. NAME OF DRILLER <i>CANAL</i>				14. TOTAL NUMBER CORE BOXES			
6. DIRECTION OF HOLE ☒ VERTICAL ☐ INCLINED _____ DEG. FROM VERT.				15. ELEVATION GROUND WATER <i>Tide + 20</i>		16. DATE HOLE	
				STARTED <i>15 May 78</i>		COMPLETED <i>15 May 78</i>	
7. THICKNESS OF OVERBURDEN				17. ELEVATION TOP OF HOLE			
8. DEPTH DRILLED INTO ROCK				18. TOTAL CORE RECOVERY FOR BORING			
9. TOTAL DEPTH OF HOLE <i>56.5</i>				19. SIGNATURE OF INSPECTOR <i>[Signature]</i>			

ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOVERY e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g
			<i>water depth 12.0</i>			<i>0.0 to 40.0 3" slt</i>
			<i>12.0 to 27.5</i>			<i>40.0 to 49.0 sand</i>
			<i>Shell: GR. CL v/soft</i>	<i>12.0</i>	<i>0.0</i>	<i>SPRAN</i>
				<i>J-1</i>		<i>49.0 to 56.5 3" slt</i>
						<i>40' 4" casing set</i>
				<i>15.0</i>		<i>EPR sample</i>
						<i>Jug #1</i>
						<i>12.0 to 14.0</i>
			<i>GR. CL (C4) v/soft</i>	<i>2-C</i>	<i>0.0</i>	<i>Jug #2</i>
				<i>17.5</i>		<i>30 to 37.5</i>
					<i>0.0</i>	<i>Jug #3</i>
				<i>3-C</i>		<i>37.5 to 49.0</i>
				<i>20.0</i>		<i>Jug #4</i>
					<i>0.0</i>	<i>51.5 to 56.5</i>
				<i>4-C</i>		
				<i>22.5</i>		
					<i>0.0</i>	
				<i>5-C</i>		
				<i>25.0</i>		
					<i>0.0</i>	
			<i>GR. CL (C4) v/soft w/ organic matter</i>	<i>6-C</i>		
			<i>27.5 to 32.5</i>	<i>27.5</i>		
					<i>0.0</i>	
			<i>GR. SO. CL Med</i>	<i>7-C</i>	<i>1.50</i>	

DRILLING LOG		DIVISION <i>Southwest</i>	INSTALLATION <i>CAV DIO</i>	Hole No. <i>78-131</i>	SHEET <i>2</i> OF <i>3</i> SHEETS
1. PROJECT <i>Woods St. Ch</i>			10. SIZE AND TYPE OF BIT		
2. LOCATION (Coordinates or Station)			11. DATUM FOR ELEVATION SHOWN (TBM or MSL)		
3. DRILLING AGENCY <i>U.S. CEC</i>			12. MANUFACTURER'S DESIGNATION OF DRILL		
4. HOLE NO. (As shown on drawing title and file number) <i>78-131</i>			13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED UNDISTURBED
5. NAME OF DRILLER <i>CP</i>			14. TOTAL NUMBER CORE BOXES		
6. DIRECTION OF HOLE ☐ VERTICAL ☐ INCLINED _____ DEG. FROM VERT.			15. ELEVATION GROUND WATER		
7. THICKNESS OF OVERBURDEN			16. DATE HOLE STARTED COMPLETED		
8. DEPTH DRILLED INTO ROCK			17. ELEVATION TOP OF HOLE		
9. TOTAL DEPTH OF HOLE			18. TOTAL CORE RECOVERY FOR BORING %		
			19. SIGNATURE OF INSPECTOR		

ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOVERY e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g
			GR. SO. CLCCH) STIFF	8-C	1.75	
				32.5	2.50	
	35.0			35.0		
				10-C	2.50	
				37.5		
	37.5 to 49.0					
			TAN SA(CSP)	11-J		
	40.0			40.0		
						SPLD S POON 40.0 To 49.0
				12-J		40.5 to 41.0 9 KL 41.0 to 41.5 11 KL
	45.0			45.0		
				13-J		45.5 to 46.0 9 KL 46.0 to 46.5 10 KL
	49.0 to 51.5					
	50.1		LA. SA. CLCCH) STIFF	49.1		49.0 to 56.5 3' 0"

DRILLING LOG		DIVISION	INSTALLATION		SHEET 3 OF 3 SHEETS	
1. PROJECT		Southwest		GALO Dist		
2. LOCATION (Coordinates or Station)		Hovata Sh. Ch		10. SIZE AND TYPE OF BIT		
3. DRILLING AGENCY				11. DATUM FOR ELEVATION SHOWN (TBM or MSL)		
4. HOLE NO. (As shown on drawing title and file number)		78-131		12. MANUFACTURER'S DESIGNATION OF DRILL		
5. NAME OF DRILLER				13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		
6. DIRECTION OF HOLE				DISTURBED		
7. THICKNESS OF OVERBURDEN				UNDISTURBED		
8. DEPTH DRILLED INTO ROCK				14. TOTAL NUMBER CORE BOXES		
9. TOTAL DEPTH OF HOLE				15. ELEVATION GROUND WATER		
				16. DATE HOLE		
				STARTED		
				COMPLETED		
				17. ELEVATION TOP OF HOLE		
				18. TOTAL CORE RECOVERY FOR BORING		
				19. SIGNATURE OF INSPECTOR		

ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOV- ERY	BOX OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant)
a	b	c	d	e	f	g
				C-14		
				51.5		
			BA. C2 (CH)		2.50	
			V/S.F.F	C-15		
				54.0		
					2.50	
				C-16		
				56.5		
						Bottom @ 56.5

