







COBBLES	GRAVEL		SAND			SILT OR CLAY
	coarse	fine	coarse	medium	fine	


Specimen Identification		Classification					LL	PL	PI	Cc	Cu	
●	B-8	6.0										
Specimen Identification		D100	D60	D30	D10	%Gravel	%Sand	%Silt	%Clay			
●	B-8	6.0	4.75	0.185		0.0	67.0	32.0				



Rock Engineering and Testing Laboratory, Inc.
4910 Neptune Street
Corpus Christi, Texas 78405
Telephone: (361) 883-4555
Fax: (361) 883-4711

GRAIN SIZE DISTRIBUTION

Project: Sunfish Island/McGee Beach Restoration
Location: Corpus Christi, Texas
Number: C0200586



COBBLES	GRAVEL		SAND			SILT OR CLAY
	coarse	fine	coarse	medium	fine	

Specimen Identification	Classification	LL	PL	PI	Cu	Cc
● B-8 7.0						


Specimen Identification	D100	D60	D30	D10	%Gravel	%Sand	%Silt	Clay
● B-8 7.0	4.75	0.133	0.091		0.0	86.0	14.0	




Rock Engineering and Testing Laboratory, Inc.
 4910 Neptune Street
 Corpus Christi, Texas 78405
 Telephone: (361) 883-4555
 Fax: (361) 883-4711

GRAIN SIZE DISTRIBUTION

Project: Sunfish Island/McGee Beach Restoration
 Location: Corpus Christi, Texas
 Number: C0200586





COBBLES	GRAVEL		SAND			SILT OR CLAY
	coarse	fine	coarse	medium	fine	

Specimen Identification		Classification	LL	PL	PI	Cc	Cu
●	B-8 9.0						

[illegible]

Rock Engineering and Testing Laboratory, Inc.
4910 Neptune Street
Corpus Christi, Texas 78405
Telephone: (361) 883-4555
Fax: (361) 883-4711

GRAIN SIZE DISTRIBUTION

Project: Sunfish Island/McGee Beach Restoration
Location: Corpus Christi, Texas
Number: C0200586