




| COBBLES | GRAVEL |      | SAND   |        |      | SILT OR CLAY |
|---------|--------|------|--------|--------|------|--------------|
|         | coarse | fine | coarse | medium | fine |              |

| Specimen Identification |     | Classification |  |  |  | LL | PL | PI | Cc | Cu |
|-------------------------|-----|----------------|--|--|--|----|----|----|----|----|
| ●                       | B-1 | 3.0            |  |  |  |    |    |    |    |    |
|                         |     |                |  |  |  |    |    |    |    |    |
|                         |     |                |  |  |  |    |    |    |    |    |
|                         |     |                |  |  |  |    |    |    |    |    |


| Specimen Identification |     | D100 | D60  | D30   | D10   | %Gravel | %Sand | %Silt | %Clay |
|-------------------------|-----|------|------|-------|-------|---------|-------|-------|-------|
| ●                       | B-1 | 3.0  | 4.75 | 0.111 | 0.085 | 0.0     | 84.0  | 16.0  |       |
|                         |     |      |      |       |       |         |       |       |       |
|                         |     |      |      |       |       |         |       |       |       |
|                         |     |      |      |       |       |         |       |       |       |



Rock Engineering and Testing Laboratory, Inc.  
 4910 Neptune Street  
 Corpus Christi, Texas 78405  
 Telephone: (361) 883-4555  
 Fax: (361) 883-4711

### GRAIN SIZE DISTRIBUTION

Project: Sunfish Island/McGee Beach Restoration  
 Location: Corpus Christi, Texas  
 Number: C0200586



| COBBLES | GRAVEL |      | SAND   |        |      | SILT OR CLAY |
|---------|--------|------|--------|--------|------|--------------|
|         | coarse | fine | coarse | medium | fine |              |

| Specimen Identification |     | Classification |  |  |  | LL | PL | PI | Cc | Cu |
|-------------------------|-----|----------------|--|--|--|----|----|----|----|----|
| ●                       | B-1 | 4.0            |  |  |  |    |    |    |    |    |
|                         |     |                |  |  |  |    |    |    |    |    |
|                         |     |                |  |  |  |    |    |    |    |    |
|                         |     |                |  |  |  |    |    |    |    |    |


| Specimen Identification |     | D100 | D60  | D30   | D10 | %Gravel | %Sand | %Silt | %Clay |
|-------------------------|-----|------|------|-------|-----|---------|-------|-------|-------|
| ●                       | B-1 | 4.0  | 4.75 | 0.172 | 0.1 | 0.0     | 87.0  | 13.0  |       |
|                         |     |      |      |       |     |         |       |       |       |
|                         |     |      |      |       |     |         |       |       |       |
|                         |     |      |      |       |     |         |       |       |       |



Rock Engineering and Testing Laboratory, Inc.  
 4910 Neptune Street  
 Corpus Christi, Texas 78405  
 Telephone: (361) 883-4555  
 Fax: (361) 883-4711

### GRAIN SIZE DISTRIBUTION

Project: Sunfish Island/McGee Beach Restoration  
 Location: Corpus Christi, Texas  
 Number: C0200586



| COBBLES | GRAVEL |      | SAND   |        |      | SILT OR CLAY |
|---------|--------|------|--------|--------|------|--------------|
|         | coarse | fine | coarse | medium | fine |              |

| Specimen Identification | Classification | LL | PL | PI | Cc   | Cu   |
|-------------------------|----------------|----|----|----|------|------|
| ● B-1 5.0               |                |    |    |    | 0.81 | 2.47 |
|                         |                |    |    |    |      |      |
|                         |                |    |    |    |      |      |
|                         |                |    |    |    |      |      |


| Specimen Identification | D100 | D60   | D30  | D10   | %Gravel | %Sand | %Silt | %Clay |
|-------------------------|------|-------|------|-------|---------|-------|-------|-------|
| ● B-1 5.0               | 4.75 | 0.192 | 0.11 | 0.078 | 0.0     | 92.0  | 8.0   |       |
|                         |      |       |      |       |         |       |       |       |
|                         |      |       |      |       |         |       |       |       |
|                         |      |       |      |       |         |       |       |       |



Rock Engineering and Testing Laboratory, Inc.  
4910 Neptune Street  
Corpus Christi, Texas 78405  
Telephone: (361) 883-4555  
Fax: (361) 883-4711

## GRAIN SIZE DISTRIBUTION

Project: Sunfish Island/McGee Beach Restoration  
Location: Corpus Christi, Texas  
Number: C0200586



| COBBLES | GRAVEL |      | SAND   |        |      | SILT OR CLAY |
|---------|--------|------|--------|--------|------|--------------|
|         | coarse | fine | coarse | medium | fine |              |

| Specimen Identification | Classification | LL | PL | PI | Cc | Cu |
|-------------------------|----------------|----|----|----|----|----|
| ● B-1 6.0               |                |    |    |    |    |    |
|                         |                |    |    |    |    |    |
|                         |                |    |    |    |    |    |
|                         |                |    |    |    |    |    |

[illegible]


**Rock Engineering and Testing Laboratory, Inc.**  
4910 Neptune Street  
Corpus Christi, Texas 78405  
Telephone: (361) 883-4555  
Fax: (361) 883-4711

## GRAIN SIZE DISTRIBUTION

Project: Sunfish Island/McGee Beach Restoration

**Location:** Corpus Christi, Texas

Number: C0200586



| COBBLES | GRAVEL |      | SAND   |        |      | SILT OR CLAY |
|---------|--------|------|--------|--------|------|--------------|
|         | coarse | fine | coarse | medium | fine |              |

| Specimen Identification | Classification | LL | PL | PI |
|-------------------------|----------------|----|----|----|
| ● B-1 7.0               |                |    |    |    |
|                         |                |    |    |    |
|                         |                |    |    |    |
|                         |                |    |    |    |


| Specimen Identification | D100 | D60   | D30   | D10 | %Gravel | %Sand | %Silt |
|-------------------------|------|-------|-------|-----|---------|-------|-------|
| ● B-1 7.0               | 4.75 | 0.115 | 0.084 |     | 0.0     | 81.0  | 19.0  |
|                         |      |       |       |     |         |       |       |
|                         |      |       |       |     |         |       |       |
|                         |      |       |       |     |         |       |       |




Rock Engineering and Testing Laboratory, Inc.  
4910 Neptune Street  
Corpus Christi, Texas 78405  
Telephone: (361) 883-4555  
Fax: (361) 883-4711

## GRAIN SIZE DISTRIBUTION

Project: Sunfish Island/McGee Beach Restoration  
Location: Corpus Christi, Texas  
Number: C0200586





| COBBLES | GRAVEL |      | SAND   |        |      | SILT OR CLAY |
|---------|--------|------|--------|--------|------|--------------|
|         | coarse | fine | coarse | medium | fine |              |

| Specimen Identification |     | Classification |      |       |       | LL      | PL    | PI    | Cc    | Cu |
|-------------------------|-----|----------------|------|-------|-------|---------|-------|-------|-------|----|
| ●                       | B-1 | 9.0            |      |       |       |         |       |       |       |    |
|                         |     |                |      |       |       |         |       |       |       |    |
|                         |     |                |      |       |       |         |       |       |       |    |
|                         |     |                |      |       |       |         |       |       |       |    |
| Specimen Identification |     | D100           | D60  | D30   | D10   | %Gravel | %Sand | %Silt | %Clay |    |
| ●                       | B-1 | 9.0            | 4.75 | 0.107 | 0.079 | 0.0     | 75.0  | 25.0  |       |    |
|                         |     |                |      |       |       |         |       |       |       |    |
|                         |     |                |      |       |       |         |       |       |       |    |
|                         |     |                |      |       |       |         |       |       |       |    |



Rock Engineering and Testing Laboratory, Inc.  
4910 Neptune Street  
Corpus Christi, Texas 78405  
Telephone: (361) 883-4555  
Fax: (361) 883-4711

### GRAIN SIZE DISTRIBUTION

Project: Sunfish Island/McGee Beach Restoration  
Location: Corpus Christi, Texas  
Number: C0200586