

- 12 - July 1971 .

GDLR NO 1636

PROJECT: ECKERTS BAYOU

BORING NO. 78-294A

TEST DATA SUMMARY

LOCATION:

DATE COMPLETED _____

[illegible]

CONSISTENCY - COHESIVE SOILS						CONSISTENCY - NONCOHESIVE SOILS				
VS	S	KL	ST	VST	H	VL	L	M	D	VD
Very Soft	Soft	Medium	Stiff	Very Stiff	Hard	Very Loose	Loose	Medium	Dense	Very Dense

(1) Tons/Sq.Ft. Unconfined Compressive Strength
(2) Split Portal Sampler
(3) Acc. Wt. Retd. ÷ Init. Wt. x 100 = % Retd.

BORING NO. 78-294A

Bottomed at	Water at	Tide Reading
-------------	----------	--------------

Sheet 1 of sheets 1

DELAY TESTS

Hole No. 79-274A

DRILLING LOG		DIVISION		INSTALLATION		SHEET	
1. PROJECT		2. LOCATION (Coordinates or Station)		3. DRILLING AGENCY		4. HOLE NO. (As shown on drawing title and file number)	
5. NAME OF DRILLER		6. DIRECTION OF HOLE		7. THICKNESS OF OVERBURDEN		8. DEPTH DRILLED INTO ROCK	
9. TOTAL DEPTH OF HOLE		10. SIZE AND TYPE OF BIT		11. DATUM FOR ELEVATION SHOWN (TBM or MSL)		12. MANUFACTURER'S DESIGNATION OF DRILL	
13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		14. TOTAL NUMBER CORE BOXES		15. ELEVATION GROUND WATER		16. DATE HOLE	
17. ELEVATION TOP OF HOLE		18. TOTAL CORE RECOVERY FOR BORING		19. SIGNATURE OF INSPECTOR		20. REMARKS	
ELEVATION	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	% CORE RECOVERY	BOX OR SAMPLE NO.	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant)	
a	b	c	d	e	f	g	
			275 TO 302 BROWN gray clay with cal. nods <u>STIFF</u>	1.50 30%	1-C	02 TO 302 3" Shelby Tube Washed Hole Down To 275 Pushed 1 sample Run Elect Log	