

DRILLING LOG		DIVISION		INSTALLATION		SHEET 1 OF 1 SHEETS	
1. PROJECT Neches River Salt Water Barrier				10. SIZE AND TYPE OF BIT 6 1/2" Dia			
2. LOCATION (Coordinates or Station) Renovet Texas				11. DATUM FOR ELEVATION SHOWN (TBM or MSL)			
3. DRILLING AGENCY U.S.C.F.C.				12. MANUFACTURER'S DESIGNATION OF DRILL Hand Auger			
4. HOLE NO. (As shown on drawing title and file number) 82-24				13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED 4 Fans	
5. NAME OF DRILLER Black				14. TOTAL NUMBER CORE BOXES		UNDISTURBED 0	
6. DIRECTION OF HOLE ☒ VERTICAL ☐ INCLINED _____ DEG. FROM VERT.				15. ELEVATION GROUND WATER		16. DATE HOLE 23 Feb 82	
7. THICKNESS OF OVERBURDEN				17. ELEVATION TOP OF HOLE		COMPLETED 23 Feb 82	
8. DEPTH DRILLED INTO ROCK				18. TOTAL CORE RECOVERY FOR BORING		%	
9. TOTAL DEPTH OF HOLE 30.0				19. SIGNATURE OF INSPECTOR But Black			
ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOVERY e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g	
			3.0 to 8.0 Black mucky clccch; soupy w/ soft		1-J	water + 3.0	
	8.0		8.0 to 11.0 GR. SA. w/TK DRGANG mud		2-J		
	11.0		11.0 to 13.0 BR: CR. SA. CLCCCL		3-I		
	13.0		13.0 to 16.0 BR. SA. CLCCCL STIFF		4-J		
	16.0		16.0 to 30.0 CR. sand w/ dense No Recv			washed 16.0 to 30.0 with JOGER Pump. No Resistance in Material	
	30.0		Bottom @ 30.0				