

DRILLING LOG		DIVISION Southwestern	INSTALLATION Galv Dist, Eng Div	SHEET OF SHEETS
1. PROJECT Wallisville Reservoir		10. SIZE AND TYPE OF BIT		
2. LOCATION (Coordinates or Station)		11. DATUM FOR ELEVATION SHOWN (TBM or MSL)		
3. DRILLING AGENCY Dept of the Army, GD, Corps of Engineers		12. MANUFACTURER'S DESIGNATION OF DRILL		
4. HOLE NO. (As shown on drawing title and file number) 3ST-356		13. TOTAL NO. OF OVERBURDEN SAMPLES TAKEN	DISTURBED 1 Jar	UNDISTURBED 2 Cont
5. NAME OF DRILLER Black		14. TOTAL NUMBER CORE BOXES		
6. DIRECTION OF HOLE <input type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED _____ DEG. FROM VERT.		15. ELEVATION GROUND WATER		
7. THICKNESS OF OVERBURDEN		16. DATE HOLE STARTED 13 Sept COMPLETED 13 Sept 1967		
8. DEPTH DRILLED INTO ROCK		17. ELEVATION TOP OF HOLE		
9. TOTAL DEPTH OF HOLE 10.0		18. TOTAL CORE RECOVERY FOR BORING %		
		19. SIGNATURE OF INSPECTOR		

ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOVERY e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g
0.0	2.0		Gray clay w/org. mat. roots stiff			Cont. 1 1.50
2.0	4.0		Gray clay w/sandy layers medium			Cont. 2 0.75
4.0	10.0		Pushed auger to 10.0 turned once and came out of hole gray sand, loose BOTTOMED Water 3.5			Jar 1