

BORING LOG FIELD DATA											
Project <u>LA QUINTA CHANNEL</u>						Location <u>SP 301451 955 LEFT</u>			Date <u>18 JULY 1972</u>		
Drill Rig <u>FAILING 1500</u>						Inspector <u>MINOR</u>			Operator <u>SMITH</u>		
Levee District <u>GALVESTON</u>						Job No. _____			Surface elev <u>TIDE + 2.5</u>		
						Boring No. <u>72-114</u>					
SAMPLE NUMBER	DATE TAKEN	STRATUM		DRIVE		SAMPLE		TYPE OF SAMPLER	CONTAINER	POCKET PENETROMETER VALUE	CLASSIFICATION AND REMARKS
		FROM	TO	FROM	TO	FROM	TO				
		0.0	17.5								WATER
1	18 JULY	17.5		17.5	23.9	17.5	23.9	3" SHELBY TUBE	TAR	0.0	GRAY SANDY CLAY. TWO PADS. KELLY AND TUBE DROPPED TO 23.9.
				23.9	26.5						WASHED
2	18 JULY	28.5		26.5	29.0	27.8	29.0	3" SHELBY TUBE	CONT	3.00	GREEN-TAN MOTTLED CLAY WITH FERRUGINOUS NODULES. BECOMING SAND AT 28.5 TAN SAND WITH INDURATED
		28.5		29.0	32.0						
3	"			32.0	34.5	33.4	34.4	3" SHELBY TUBE	CONT	4.50	PARTL. AND CLAYEY LAMINAE WASHED
		36.5		34.5	37.5						
4	"	36.5		37.5	40.0	38.8	40.0	3" SHELBY TUBE	CONT	2.50	GRAY-TAN BENTONITE CLAY WITH CALCAREOUS NODULES WASHED
				42.0	40.0	43.0					
5	"	42.0		43.0	45.5	44.3	45.4	3" SHELBY TUBE	CONT	2.25	GRAY TAN MOTTLED SANDY BENTONITE CLAY WITH SAND LAYERS. WASHED
				45.5	48.5						
6				48.5	51.0	48.8	51.0	3" SHELBY TUBE	CONT	2.50	WITH CALCAREOUS NODULES

Date _____ Classified by _____

[illegible]

[illegible]

Date _____ Classified by _____

[illegible]