

DRILLING LOG		DIVISION Southwestern		INSTALLATION Galv Dist, Eng Div		SHEET OF SHEETS	
1. PROJECT Houston Ship Channel, Green's Bayou				10. SIZE AND TYPE OF BIT			
2. LOCATION (Coordinates or Station)				11. DATUM FOR ELEVATION SHOWN (TBM or MSL)			
3. DRILLING AGENCY Dept of the Army, GD, Corps of Engineers				12. MANUFACTURER'S DESIGNATION OF DRILL			
4. HOLE NO. (As shown on drawing title and file number)		3ST-44		13. TOTAL NO. OF OVERBURDEN SAMPLES TAKEN		DISTURBED 3 Jars	UNDISTURBED 1 Cont
5. NAME OF DRILLER Curtis				14. TOTAL NUMBER CORE BOXES			
6. DIRECTION OF HOLE <input type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED _____ DEG. FROM VERT.				15. ELEVATION GROUND WATER			
7. THICKNESS OF OVERBURDEN				16. DATE HOLE		STARTED 2 Nov	COMPLETED 2 Nov 1967
8. DEPTH DRILLED INTO ROCK				17. ELEVATION TOP OF HOLE			
9. TOTAL DEPTH OF HOLE 22.0				18. TOTAL CORE RECOVERY FOR BORING %			
19. SIGNATURE OF INSPECTOR							
ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOVERY e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g	
0.0	10.0		Water				
10.0	12.0		Gray clay w/org. mat. v/soft weight of 10.0 rod and kelly			Jar 1	
12.0	16.0		Gray clay w/org. mat. v/soft weight of 10.0 rod and kelly pulled down by hand			Jar 2	
16.0	20.0		Same as above			Jar 3	
20.0	21.0		Same as above			No sample	
21.0	22.0		Brown and gray clay w/cal nods, soft			Cont. 1                      0.25	
			BOTTOMED				
			Water table 9.7				