

GDLX NO 1595

BORING NO. 77-222

TEST DATA SUMMARY

DATE COMPLETED

[illegible]

CONSISTENCY - COHESIVE SOILS						CONSISTENCY - COHESIONLESS SOILS				
VS	S	K	ST	VST	H	VL	L	M	D	VD
Very Soft	Soft	Medium	Stiff	Very Stiff	Hard	Very Loose	Loose	Medium	Dense	Very Dense

(1) Tons/Sq.Ft. Unconfined Compressive Strength
(2) Split Barrel Sampler
(3) Acc. Wt. Btnd ÷ Init. Wt. x 100 = % Grnd.

BORING NO. 77-222

Sheet 1 of sheets 1

Bottomed at _____ Water at _____ Tide Reading +1.2

DRILLING LOG		DIVISION Southwest	INSTALLATION COLUM. DIST.		SHEET 1 OF 1 SHEETS
1. PROJECT SABINE RIVER WATER WAY			10. SIZE AND TYPE OF BIT		
2. LOCATION (Coordinates or Station) Lat. 29° 22' 00" N Long. 93° 50' 30" W			11. DATUM FOR ELEVATION SHOWN (TBM or MSL)		
3. DRILLING AGENCY U.S. C. F. C.			12. MANUFACTURER'S DESIGNATION OF DRILL VIBRA-COR		
4. HOLE NO. (As shown on drawing title and file number) 77-222			13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED UNDISTURBED 1 Total
5. NAME OF DRILLER L. Adams			14. TOTAL NUMBER CORE BOXES		
6. DIRECTION OF HOLE ☒ VERTICAL ☐ INCLINED _____ DEG. FROM VERT.			15. ELEVATION GROUND WATER		
7. THICKNESS OF OVERBURDEN			16. DATE HOLE STARTED 7/5/77 COMPLETED 7/5/77		
8. DEPTH DRILLED INTO ROCK			17. ELEVATION TOP OF HOLE		
9. TOTAL DEPTH OF HOLE 219.8			18. TOTAL CORE RECOVERY FOR BORING 9.0		
			19. SIGNATURE OF INSPECTOR Bert L. Hall		

ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOV- ERY e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g
			0 to 42.0 water depth			
	42.0	42.0 to 49.0	CR. CL. to TAN SS. CL.		101	9.0 SAMPLE RECU
	49.0		Bottom at 59.0			