Hole No. 3ST-37C

DRILLING LOG	DIVISION Southwestern	INSTALLATION Galv Dist, Eng Div	SHEET OF SHEETS

1. PROJECT Brays Bayou	10. SIZE AND TYPE OF BIT
2. LOCATION (Coordinates or Station)	11. DATUM FOR ELEVATION SHOWN (TBM or MSL)
3. DRILLING AGENCY U. S. Army Corps of Engineers	12. MANUFACTURER'S DESIGNATION OF DRILL
4. HOLE NO. (As shown on drawing title and file number) 3ST-37C	13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN: DISTURBED 4 Jars; UNDISTURBED 1 Cont
5. NAME OF DRILLER Curtis	14. TOTAL NUMBER CORE BOXES
	15. ELEVATION GROUND WATER
6. DIRECTION OF HOLE ☐ VERTICAL ☐ INCLINED _____ DEG. FROM VERT.	16. DATE HOLE: STARTED 18 May; COMPLETED 18 May 1966
7. THICKNESS OF OVERBURDEN	17. ELEVATION TOP OF HOLE
8. DEPTH DRILLED INTO ROCK	18. TOTAL CORE RECOVERY FOR BORING %
9. TOTAL DEPTH OF HOLE 12.0	19. SIGNATURE OF INSPECTOR

ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOVERY e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g
0.0	2.0		Gray sandy clay w/org. mat. v/soft			Jar 1
2.0	4.0		Washed, same as above			No sample
4.0	6.0		Gray sandy clay w/org. mat. 4.0-4.5 Seat pent 4.5-5.0 2 blows 5.0-5.5 2 blows 5.5-6.0 Retain sample			Jar 2
6.0	7.5		Brown gray sandy clay stiff			Jar 3
7.5	8.0		Washed			No sample
8.0	10.0		Light bray sandy clay 8.0-8.5 Seat pent 8.5-9.0 5 blows 9.0-9.5 7 blows 9.5-10.0 Retain sample			Jar 4
10.0	12.0		Light gray sandy clay BOTTOMED Water 9.0			Cont. 1