Hole No. 3ST-30C

DRILLING LOG	DIVISION Southwestern	INSTALLATION Galv Dist, Eng Div	SHEET OF SHEETS

1. PROJECT Brays Bayou	10. SIZE AND TYPE OF BIT
2. LOCATION (Coordinates or Station) Houston, Texas	11. DATUM FOR ELEVATION SHOWN (TBM or MSL)
3. DRILLING AGENCY U. S. Army Corps of Engineers	12. MANUFACTURER'S DESIGNATION OF DRILL
4. HOLE NO. (As shown on drawing title and file number) 3ST-30C	13. TOTAL NO. OF OVERBURDEN SAMPLES TAKEN — DISTURBED: 6 Jars — UNDISTURBED:
5. NAME OF DRILLER Curtis	14. TOTAL NUMBER CORE BOXES
6. DIRECTION OF HOLE ☐ VERTICAL ☐ INCLINED ____ DEG. FROM VERT.	15. ELEVATION GROUND WATER
	16. DATE HOLE — STARTED: 19 May 66 — COMPLETED: 19 May 66
7. THICKNESS OF OVERBURDEN	17. ELEVATION TOP OF HOLE
8. DEPTH DRILLED INTO ROCK	18. TOTAL CORE RECOVERY FOR BORING %
9. TOTAL DEPTH OF HOLE 15.0	19. SIGNATURE OF INSPECTOR

ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOVERY e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g
0.0	2.2		Gray silty clayey sand			Jar 1
2.2	4.5		Brown gray sandy clay w/cal nod			Jar 2
4.5	7.5		Red silty clay, tr sand			Jar 3
7.5	10.0		Hit sand stone unable to go further with hand auger. Red clay w/sand stone layer			Jar 4
10.0	12.0		Red sandy silt			Jar 5
12.0	15.0		Red clay, hard			Jar 6
			Bottom			