

LOG OF BORING

PROJECT: White Point Island Restoration
Nueces Bay - Corpus Christi, Texas

CLIENT: Shiner Moseley & Associates, Inc.
Corpus Christi, Texas

PROJECT NO. 1600-0159

BORING NO. B-2

DATE 9/20/2000

ELEV. NA

SHEET 1 of 1

FIELD DATA				LABORATORY DATA								DRILLING METHOD (S) :	
SOIL SYMBOL	DEPTH (FT)	SAMPLES N: BLOWS/FT P: TONS/SQ.FT T: TORVANE FT PERCENT RECOVERY/ ROCK QUALITY DESIGNATION	MOISTURE CONTENT	ATTEBERG LIMITS (%)			DRY DENSITY POUNDS/CU.FT	SHEAR STRENGTH (KIPS/SQ.FT)	FAILURE STRAIN (%)	CONFINING PRESSURE (POUNDS/SQ.IN)	MINUS NO. 200 SIEVE (%)	GROUNDWATER INFORMATION:	
				LIQUID LIMIT	PLASTIC LIMIT	PLASTICITY INDEX						Depth of water from surface to mudline at time of drilling was 2.0 ft.	
				LL	PL	PI						DESCRIPTION OF STRATUM	
	5	N=1										Shell fragments, with sand, very loose.	
		N=1											
		N=5										-loose, below 4.5'.	
		N=3											
		N=4											
10												TOTAL DEPTH = 10 FT (Below Mudline)	
	15												
20													
N - STANDARD PENETROMETER TEST RESISTANCE P - POCKET PENETROMETER RESISTANCE T - POCKET TORVANE SHEAR STRENGTH												REMARKS: PLATE 3	