

LOG OF BORING

PROJECT: White Point Island Restoration
Nueces Bay - Corpus Christi, Texas

CLIENT: Shiner Moseley & Associates, Inc.
Corpus Christi, Texas

PROJECT NO. 1600-0159

BORING NO. B-12

DATE 9/20/2000

ELEV.	NA
-------	----

SHEET 1 of 1

FIELD DATA		LABORATORY DATA										DRILLING METHOD (S) :		
SOIL SYMBOL	DEPTH (FT)	SAMPLES	N: BLOWS/FT P: TONS/SQ FT T: TORVANE SHEAR STRENGTH PERCENT RECOVERY/ ROCK QUALITY DESIGNATION	MOISTURE CONTENT	ATTERBERG LIMITS (%)			DRY DENSITY POUNDS/CU FT	SHEAR STRENGTH (KIPS/SQ FT)	FAILURE STRAIN (%)	CONFINING PRESSURE (POUNDS/SQ IN)	MINUS NO. 200 SIEVE (%)	GROUNDWATER INFORMATION:	
					LL	PL	PI						Depth of water from surface to mudline at time of drilling was 1.5 ft.	
													DESCRIPTION OF STRATUM	
	5		N=WH	30									Clay, very soft, gray, with shell fragments.	
			N=WH	48										
			N=WH	51	37	16	21							
			N=WH	58										
	10		N=WH	33									Shell fragments, with sand and clay, gray, very loose.	
													TOTAL DEPTH = 10 FT (Below Mudline)	
	15													
	20													
N - STANDARD PENETROMETER TEST RESISTANCE P - POCKET PENETROMETER RESISTANCE T - POCKET TORVANE SHEAR STRENGTH												REMARKS:		
												PLATE 13		